

Appl. No. 10/814,092
Amld. dated December 21, 2005

Reply to Office Action of September 29, 2005
Attorney Docket 17380

Amendments to the Specification

Please amend lines 18-20 on page 9 as follows:

These components all rotate together, biased against clutch internal ratcheting mechanism +00-102 (see Figures 8 and 9).